


SPOT CONNECTIONS DIAGRAM

I N T I L E D



Wire color Input/Output

brown +48 V

white - 48 V

green PWM

Note. If the brightness control "PWM" is not used - green wire is not connected (isolated)